


1/14





OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 2 OF 14

2/14












OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 3 OF 14

3/14






4/14



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET <u>5</u> OF <u>14</u>


5/14

FIG.6 PRIOR ART




OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET <u>6</u> OF <u>14</u>


6/14



7/14



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET <u>8</u> OF <u>14</u>



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 9 OF 14

9/14 FIG.10A






FIG.10B

CONDUCTOR CONNECTED TO DRAIN REGION 20b



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 10 OF 14

10/14






OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 11 OF 14

11/14

FIG.12A



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 12 OF 14

12/14

FIG.13A






FIG.13B



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 13 OF 14

13/14

FIG.14



OBLON, SPIVAK, ET AL DOCKET #: 242511US2DIV INV: Seiichi MORI, et al. SHEET 14 OF 14

14/14

FIG.15A




FIG.15B

